

Memo



TO: Whom it may concern
FROM: Katie Mullin
DATE: 1/12/10
SUBJECT: Field expansion device change out

373 Atascocita Road
Humble, TX 77396
T 281 441-6500 x107
F 281 441-6510
kmullin@aspenmfg.com
www.aspenmfg.com

It is typical for customers to order many, if not all, of their coils with one metering device or another. They do this so when the outdoor unit is selected, if a thermal expansion valve (TXV) is necessary, they can install one for the proper refrigerant ie R-22 or R-410a. If a coil was manufactured with a R22 orifice, the coil model will reflect a "F" at the end of the coil model number or R410a orifice would indicate a "G". If a R-22 factory installed TXV, the coil model will have a "X" and R-410a would be "4".

All Aspen TXV and orifice kits include a green R22 sticker or pink R410a sticker for the installing contractor to apply to the silver mylar coil model tag. Additionally, some contractors will submit data regarding the expansion device change out upon inspection. It is important that the correct metering device is included in the coil model on the rebate form to ensure proper AHRI certification matching.

Please feel free to contact me with additional questions or comments.

A handwritten signature in cursive script that reads "Katie Mullin".

Katie Mullin
Marketing Manager